


SHEET STOCK

6" x 12" with PSA



PART NUMBER	THICKNESS	THICKNESS TOLERANCE	DURO	STOCK ITEM	NOTES
0206110-40-10	0.100	±0.020	40	•	PSA
0206110-50-10	0.100	±0.020	50	•	PSA
0206110-60-10	0.100	±0.020	60	•	PSA
0206110-70-10	0.100	±0.020	70	•	PSA
0206112-40-10	0.125	±0.025	40	•	PSA
0206112-50-10	0.125	±0.025	50	•	PSA
0206112-60-10	0.125	±0.025	60	•	PSA
0206112-70-10	0.125	±0.025	70	•	PSA
0206119-30-10	0.188	±0.025	30	•	PSA
0206119-40-10	0.188	±0.025	40	•	PSA
0206119-50-10	0.188	±0.025	50	•	PSA
0206119-60-10	0.188	±0.025	60	•	PSA
0206119-70-10	0.188	±0.025	70	•	PSA
0206126-30-10	0.250	±0.025	30	•	PSA
0206126-40-10	0.250	±0.025	40	•	PSA
0206126-50-10	0.250	±0.025	50	•	PSA
0206126-60-10	0.250	±0.025	60	•	PSA
0206126-70-10	0.250	±0.025	70	•	PSA


Sorbothane® Strips

Sorbothane® Strips offer a quick and effective method for isolating a wide variety of equipment. Choose the correct thickness, durometer and number of Strips required for the load. Sorbothane® Strips can easily be cut to size and are ideal for medium to heavy loads.



STRIPS

2" x 36"



PART NUMBER	THICKNESS	THICKNESS TOLERANCE	DURO	STOCK ITEM	NOTES
0236212-50-10	0.125	±0.015	50	•	
0236212-70-10	0.125	±0.015	70	•	
0236225-50-10	0.25	±0.020	50	•	
0236225-70-10	0.25	±0.020	70	•	
0236237-30-10	0.375	±0.025	30	•	
0236237-50-10	0.375	±0.025	50	•	
0236237-70-10	0.375	±0.025	70	•	
0236250-30-10	0.50	±0.030	30	•	
0236250-50-10	0.50	±0.030	50	•	
0236250-70-10	0.50	±0.030	70	•	